Boxford Communications Department Surplus Equipment

October 20, 2022

Condition of all equipment is unknown - has not been tested

Quantity	EQUIPMENT TYPE	STYLE	Manufacturer	Model			Model #	Serial #	Other	
2	2-way Radio	Siren Control - Remote head	Motorola	Systems 9000			HLN1241D			
2	2-way Radio	Siren Control - Remote head	Motorola	Systems 9000			HLN1241C			
1	2-way Radio	Mobile Siren System	Motorola	Systems 9000 Spectra Astro			HLN1185C			
5	2-way Radio	Mobile Siren System	Motorola	Systems 9000 Spectra Astro			HLN1185E			
1	2-way Radio	Mobile Siren System	Motorola	Systems 9000 Spectra Astro			HLN1185D		marked as "no good"	
1	2-way Radio	Siren Speaker	Federal Signal	ES100C	Series A		ES100C			
1	Monitor	40" LCD	Samsung	LH40E	No Stand		LH40EDD PLGC/ZA	028KHCMFC00620W		
1	Shredder	Cross Cut	Staples				SPL-NXC16RA	FT04320631000024	does not power on	
1	Monitor	22" LCD	Security Monitor	widescreen	No Stand		LCD215LED	215LED00812041255		
1	Monitor	19" LCD	Security Monitor	widescreen	No Stand		9005L-TD	LCD0310900500978	Powers on, no backlight	
1	Monitor	15" LCD	Dell		No Stand		E152FPc		does not power on power light flashes intermittently	
1	Monitor	19" LCD	Princeton	not widescreen	with stand		LCD1950			
1	Monitor	17" LCD	NEC	not widescreen	with stand		LCD1770VX			
1	2-way Radio	Desktop Remote	Motorola	Command Series	DC Remote		L1474A	740CNY1248		
1	Printer	B&W laser	HP	LaserJet 4050TN			4050TN			
10	pager accessory	non powered speaker	USAlert			plugs into NOVA pager charger				
13	2-way Radio	channel knob	Motorola	for XTS 1500 & 2500 portable radio						
1	2-way Radio	battery charger	iTech	for Motorola HT style radio batteries			BCIQPAC		charger/conditioner	
1	2-way Radio	Base Station radio	Motorola	Mitrek	VHF Hi Band		L73JJB3106C	447HPE0114		
1	Intercom	Intercom Master	Aiphone				MP-35		speaker sounds scratchy	
1	Plectron receiver	desktop	Plectron					R20AS-44957		5/22/1970
3	UPS		APC	Back-UPS CS350			CS350		No battery	
1	UPS		APC	Back-UPS CS500			CS500		No battery	
1	Multiplexer	T1/E1 Multiplexer	TC Communications	TC8614			TC8614	TC8614S-00-41-04-12	Corrosion on Ethernet Port	