



February 18, 2016

Boxford Conservation Commission
Attn: Ross Povenmire, Director of Conservation
7A Spofford Road
Boxford, MA 01921

Subject: Environmental Monitoring Report #8 - Boxford Common
DEP File Number 114-1166

Dear Commission Members,

On February 17, 2016 I inspected the erosion controls on-site to determine if they were functioning properly following the rain event on February 16, 2016. I walked the remaining erosion controls in Phase I and inspected the erosion controls installed for Phase II. No breaches were identified and the erosion controls are functioning properly.

Please find attached photographs that show the erosion controls installed for Phase II. As you can see from the photographs the contractors have respected the limit of work during the tree removal effort for Phase II.

Other than some minor routine maintenance to the silt fence, I do not recommend any changes to what is currently in place for Phase II. If you should have any questions regarding this information please do not hesitate to contact our office.

Sincerely,

WILLIAMS & SPARAGES, LLC

Greg J. Hochmuth, RS, PWS, CWS
Ecological Division Manager

cc: Christian C. Huntress, RLA
Alan Benson – Town of Boxford
Tom Liddy – Lucas Environmental, LLC
Jim Doherty – Rad Sports
Margaret Chow-Menzer – Town of Boxford

